



## Top Supplier Defects

Here is a list of the top defects we see on supplier details/assemblies.

### 1) The majority pertain to the holes on the detail.

- Holes **off location**
- Hole **size incorrect**. Hole is undersized or oversized
- Holes are **missing**
- Holes are missing a process for example
  - **Not tapped**
  - **Not counter bored**

### 2) Surface finish nonconformances.

- **Missing black oxide**

### 3) Valiant part number is missing or not visible on the details.

- Please ensure that after paint, black oxide or any other surface finish the **Valiant part number is still legible**.

**Please review and inspect your material for these issues. Our inspections will focus on these types of defects when we receive supplier product.**

For more information, please contact your Quality Department Representative.



#### OUR COMMITMENT

The Valiant Group and partnering companies are totally committed to, and actively participate in, the ongoing process of quality improvement, reliability, maintainability and durability.